Site Inspection Report Liquid System



Contractor:	Project I.D No:	Project Name/Title:
Belmont Roofing	4421	The Theatre Royal

Date: 17/9/14

Visit No: 2

Time of Visit: 08:00am

Duration on site 1 hr

Site Support Technician: Dave Boichat

Account Manager: Paul Gibson

Euro Polymers Systems: Eurocote SPO

No. of operatives:

EP trained operatives: 1

Further training required: No

ID cards/Names (if required): No

Others in attendance: N/A

Weather Conditions: Cloudy

Air temperature: 12 Degrees

Surface temperature: N/A

Percentage Complete: 75%

Next visit date: To be arranged



Check List Item	Observations	Comments/Recommendations
Material storage	Not viewed	
2. Damaged/wet materials	Not viewed	
3. Substrate	Acceptable	
4. Jet wash	N/A	
5. Preparation	N/A	
6. Primer	N/A	
7. VCL	N/A	
8. Adhesives	N/A	
9. Insulation	N/A	
10. Fillets	N/A	
12. Joint tape	N/A	
12. Detailing tape	N/A	
13. Rapid ST	N/A	
14. Gridding	Not viewed	
15. Base Coat application	Acceptable	Coverage rate has been applied.
16. Intermediate coat application	N/A	
17. Top Coat application	Not viewed	
18. Outlets	Acceptable	
19. Associated details	Not viewed	
20. System Termination	Acceptable	150mm dress up the upstand detail.
21. Night seal	N/A	
22. WFT	N/A	
23. DFT	N/A	
24. Other	N/A	

Applicator feedback (for office use only)

Application issues	N/A
Product issues	N/A

Images



Anti-slip walk way has been installed on top of the Eurocote SPO Base Coat. Awaiting the Top Coat over full area.



Eurocote SPO has been applied to the existing substrate and coverage has been achieved.



Eurocote SPO Base Coat has been applied to the detail work to a good standard.



Coating has been dressed 150mm up the upstand detail.



Good application work around detail.



Detail work on the roof in which the Eurocote SPO Base Coat has been applied to a good standard.



Good coverage rate has been achieved.



More detail work where the Eurocote SPO has been applied to a good standard.



New outlet has been installed and the Base Coat has been applied to a good standard.